



091 830684
COFC



Certificate
JUN 14 2006
of Correction

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313

Docket No.: 206379US40PCT

RE: Inventor: Masato TAKAHASHI
Patent No.: 6,999,162
Issued: February 14, 2006
Group Art Unit: 2851
Examiner: KIM, PETER B
For: STAGE DEVICE, EXPOSURE SYSTEM, METHOD
OF DEVICE MANUFACTURE, AND DEVICE

SIR:

Attached hereto for filing are the following papers:

REQUEST FOR CERTIFICATE OF CORRECTION
CERTIFICATE OF CORRECTION FORM PTO 1050

Our check in the amount of \$0.00 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.



Richard D. Kelly

Registration No. 27,757

Raymond F. Cardillo, Jr.
Registration No. 40,440

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/06)

DOCKET NO.: 206379US40PCT/sm



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: **Masato TAKAHASHI**

PATENT NO.: **6,999,162**

GROUP: **2851**

ISSUED: **February 14, 2006**

EXAMINER: **KIM, PETER B**

FOR: **STAGE DEVICE, EXPOSURE SYSTEM, METHOD OF DEVICE
MANUFACTURE, AND DEVICE**

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE
ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 09/830,684, now U.S. Patent Number 6,999,162.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.

Raymond F. Cardillo, Jr.
Richard D. Kelly

Registration No. 27,757
Raymond F. Cardillo, Jr.
Registration No. 40,440

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/06)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : **6,999,162**

DATED: **Feb. 14, 2006**

INVENTOR(S): **Takahashi**

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (75), the inventor's residence is incorrect. Item (75) should read:

-- (75) Inventor: **Masato Takahashi, Kumagaya (JP)** --

Mailing address of sender:

Patent No. **6,999,162**

Customer Number

22850

No. of add'l copies
@ .30 per page

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/06)



JUN 16 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : **6,999,162**

DATED: **Feb. 14, 2006**

INVENTOR(S): **Takahashi**

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (75), the inventor's residence is incorrect. Item (75) should read:

-- (75) Inventor: **Masato Takahashi, Kumagaya (JP)** --

Mailing address of sender:

Patent No. **6,999,162**

Customer Number

22850

No. of add'l copies
@ .30 per page

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/06)

